




Position 1 Menge 1
K-Pos Fe: WZ/Aufsatzr. Kurbel li.




Position 2 Menge 1
K-Pos Fe: WZ/Aufsatzr. Kurbel re.



Position 3 Menge 1
K-Pos Aufsatzrollo: für Pos.1 lose



Position 4 Menge 1
K-Pos Fe: EZ/Ausatzr. Kurbel li.



Position 5 Menge 1
K-Pos Fe: SZ/Ausatzr. Kurbel re.

